

Lakeland ARC/FR High Vis Rainwear Care Guide

Care and Cleaning Information for Lakeland[®] Arc/FR Hi-Visibility Rainwear

General cleaning information:

- Spot clean or wipe entire garment using a damp cloth.
- For more thorough cleaning, garments can be home laundered in cold water, gentle cycle.
- **Do not use** abrasive cleaners, solvents, bleach, or fabric softeners.
- **Do not** iron.
- **Do not** dry clean or clean in an industrial laundry facility.

Home Laundering Instructions:

1. Wash separately from other garments and/or close zipper and hook & loop to reduce the risk of damaging the garment, or other garments.
2. Machine wash in cold water (104°F, 40°C).*
3. Use mild detergent on gentle cycle.
4. Hang garment inside-out to air dry. **Do not** dry garment in machine dryer.

Lakeland Arc/FR High Vis Rainwear may not be repaired. When wearing FR garments, if they become damaged, ripped, torn or compromised with flammable materials they should immediately be removed from service and replaced with clean FR garments.